

## Heat Shrink Boots

Heavy Wall	Medium Wall
.35	.375
.40	.75
.50	1.0
.75	1.5
1.1	2
1.3	2.5
1.5	3.5
1.7	5
2.05	6
2.75	
3.5	
4.7	

With or without adhesive

We can also supply shrinkable boots, feedthroughs and transitions. Including multilegged transitions, T and Y transitions , three and four transitions.